



Overview of building from southeast




Overview of northwest side of building



Overview of northeast side of building



Overview of building from southwest



Temporary enclosure for interior climate control




Vestibule tile wall



Fire alarm conduits installed



Duty lockers installed. Bench and top to be installed



Mechanical mezzanine swing gate fabricated



Water testing at watch room




Backflow preventer behind water tanks moved down and bypass removed. Water dept coordinated



Set up for bunk room window testing



Mechanical mezzanine pipe insulation



Fire alarm bell installed



Typical fire sprinkler finishing



Taping bathroom wall joints for thin set mortar